

1 Q. **Project C-53: Upgrade Corner Brook Frequency Converter, Corner Brook**

2 With reference to Appendix A - 2015 Siemens Report, Vol. II, Tab 15, pages A7-A8.
3 Siemens recommendations do not, at least on their face, encompass the rotor
4 wedging, replacement of bellows and installation of fans and air ducting
5 components of this proposed Project. Are there any findings of the Siemens report
6 which, in Hydro's view, support these components of the Project, and if not, what is
7 Hydro's supporting expert assessment for these components of the Project?

8

9

10 A. The proposal to replace rotor pole wedges followed a verbal recommendation by
11 Siemens in 2014, when it was discovered that retaining wedges between the spider
12 and pole assemblies on the rotor had become loose and required temporary re-
13 setting of the wedges in order to put the converter back in service.

14

15 The Siemens Report, 15-027, concentrated primarily on electrical testing of the 50
16 Hz and 60 Hz synchronous machines (rotors and stators) and the rotating DC
17 exciters. Transformer cooling was not included in the scope of Siemen's 2015
18 condition study. Rather, operations personnel at Hydro have observed
19 temperatures on Corner Brook transformers T1 and T2 to be tracking higher than
20 normal in recent years. Hydro's internal technical opinion is that the higher than
21 normal temperatures on these air-cooled units are linked to less than optimum air
22 circulation in the transformer vault area. As transformer temperature is directly
23 related to loading and ambient air temperature, much higher operating
24 temperatures can be expected when the converter is upgraded and operated at full
25 capacity, if the upgrading is not completed. The proposed ventilation upgrades will
26 enhance transformer cooling and slow transformer deterioration due to
27 overheating.

1 Replacement of the flexible connections between the alternator air outlets and the
2 air ducting system is required to maintain the integrity of the sealed air ducting
3 system. The components in question are the original flexible connections and have
4 been subjected to repeated mechanical and thermal stresses over the years, to the
5 point where the fabric has ruptured allowing hot air and dust from the synchronous
6 machines to enter the building. As well, the flexible connections contain 60 %
7 chrysotile asbestos, which requires replacement with a non asbestos materials, due
8 to safety and health concerns.