1	Q.	Re	ference: Reliability and Resource Adequacy Study 2022 Update, Volume III, page 16.
2		Pro	ovide the most recent update on the status of the commissioning of the LIL including:
3		a)	A description of the cause of the November 24, 2022 LIL offline event, the actions taken to
4			correct the software failure that led to the event and how this affects the commissioning
5			schedule, and
6		b)	The cause of the overheard line damage on the LIL in the Northern Peninsula discovered on
7			December 2, 2022, its implications for other LIL line sections and the action Hydro is taking
8			to investigate this incident and its implications for overall LIL reliability.
9			
10			
11	A.	a)	GE Canada ("GE") has completed a root-cause analysis and pinpointed the problem to a
12			measurement/calculation issue when operating the Labrador-Island Link ("LIL") above
13			475 MW. An analysis of the event shows:
14			• Pole 2 fully compensated for the planned emergency stop of Pole 1;
15 16			 Pole 2 operated at 700 MW for approximately 44 seconds until a block occurred; and
17			• Pole 2 was blocked because of several commutation failures in rapid succession.
18			It has been determined there is a control system calculation issue related to the extinction
19			angle. To correct the problem, a new software version is required. This new software
20			version will need to go through regression testing and Factory Acceptance Testing. Once
21			Factory Acceptance Testing is successfully completed and the software is released to the
22			site, the LIL will undergo Dynamic Commissioning at available power levels; however,
23			completion of another Trial Operations period is not commercially required. A series of tests
24			to prove overload functionality will be performed including a repeat of the 700 MW
25			overload test. In addition, there will be tests conducted to prove extinction angle
26			measurements are accurate.

1		The regression testing and Factory Acceptance Testing have been completed on the new
2		version of the software, with the control system calculation issue related to the extinction
3		angle successfully corrected. The software release to site is delayed pending the completion
4		of root cause analysis by GE for LIL trips that occurred on January 31, 2023 and February 2,
5		2023. Once the root-cause analysis has been completed and any identified corrective
6		actions implemented, the software will be released to site and Dynamic Commissioning will
7		commence. The plan is to release the new version of the software and complete high-power
8		testing in the first quarter of 2023. Newfoundland and Labrador Hydro ("Hydro") will
9		provide a further update on the schedule, which requires coordination with its peer utilities
10		in Atlantic Canada at least ten days in advance, in the next LIL monthly update to the Board
11		of Commissioners of Public Utilities.
12		Hydro will continue to work with GE and other stakeholders to plan for the completion of
13		the high-power tests required to achieve Final Commissioning.
14	b)	Repairs to the damage discovered on December 2, 2022 have been completed; however,
14 15	b)	Repairs to the damage discovered on December 2, 2022 have been completed; however, the root cause analysis is ongoing, as Hydro has experienced similar issues elsewhere on the
14 15 16	b)	Repairs to the damage discovered on December 2, 2022 have been completed; however, the root cause analysis is ongoing, as Hydro has experienced similar issues elsewhere on the line.
14 15 16 17	b)	Repairs to the damage discovered on December 2, 2022 have been completed; however, the root cause analysis is ongoing, as Hydro has experienced similar issues elsewhere on the line. As reported in the <i>"Reliability and Resource Adequacy Study Review</i> – Labrador-Island Link
14 15 16 17 18	b)	Repairs to the damage discovered on December 2, 2022 have been completed; however, the root cause analysis is ongoing, as Hydro has experienced similar issues elsewhere on the line. As reported in the <i>"Reliability and Resource Adequacy Study Review</i> – Labrador-Island Link Monthly Update - December 2022," ¹ similar to the December 2, 2022 issue, Hydro has since
14 15 16 17 18 19	b)	Repairs to the damage discovered on December 2, 2022 have been completed; however, the root cause analysis is ongoing, as Hydro has experienced similar issues elsewhere on the line. As reported in the <i>"Reliability and Resource Adequacy Study Review –</i> Labrador-Island Link Monthly Update - December 2022," ¹ similar to the December 2, 2022 issue, Hydro has since found two additional broken turnbuckles and unbroken conductors on the ground, one in
14 15 16 17 18 19 20	b)	Repairs to the damage discovered on December 2, 2022 have been completed; however, the root cause analysis is ongoing, as Hydro has experienced similar issues elsewhere on the line. As reported in the <i>"Reliability and Resource Adequacy Study Review –</i> Labrador-Island Link Monthly Update - December 2022," ¹ similar to the December 2, 2022 issue, Hydro has since found two additional broken turnbuckles and unbroken conductors on the ground, one in southern Labrador on Pole 1 and another in the Long Range Mountains on the Island.
14 15 16 17 18 19 20 21	b)	Repairs to the damage discovered on December 2, 2022 have been completed; however, the root cause analysis is ongoing, as Hydro has experienced similar issues elsewhere on the line. As reported in the <i>"Reliability and Resource Adequacy Study Review</i> – Labrador-Island Link Monthly Update - December 2022," ¹ similar to the December 2, 2022 issue, Hydro has since found two additional broken turnbuckles and unbroken conductors on the ground, one in southern Labrador on Pole 1 and another in the Long Range Mountains on the Island. Repairs have since been completed. ²
14 15 16 17 18 19 20 21 22	b)	Repairs to the damage discovered on December 2, 2022 have been completed; however, the root cause analysis is ongoing, as Hydro has experienced similar issues elsewhere on the line. As reported in the <i>"Reliability and Resource Adequacy Study Review</i> – Labrador-Island Link Monthly Update - December 2022," ¹ similar to the December 2, 2022 issue, Hydro has since found two additional broken turnbuckles and unbroken conductors on the ground, one in southern Labrador on Pole 1 and another in the Long Range Mountains on the Island. Repairs have since been completed. ² As mentioned, a root-cause investigation into each of the noted issues is underway. The
14 15 16 17 18 19 20 21 22 23	b)	Repairs to the damage discovered on December 2, 2022 have been completed; however, the root cause analysis is ongoing, as Hydro has experienced similar issues elsewhere on the line. As reported in the <i>"Reliability and Resource Adequacy Study Review</i> – Labrador-Island Link Monthly Update - December 2022," ¹ similar to the December 2, 2022 issue, Hydro has since found two additional broken turnbuckles and unbroken conductors on the ground, one in southern Labrador on Pole 1 and another in the Long Range Mountains on the Island. Repairs have since been completed. ² As mentioned, a root-cause investigation into each of the noted issues is underway. The information from the root-cause investigations will be used to determine appropriate
14 15 16 17 18 19 20 21 22 23 24	b)	Repairs to the damage discovered on December 2, 2022 have been completed; however, the root cause analysis is ongoing, as Hydro has experienced similar issues elsewhere on the line. As reported in the " <i>Reliability and Resource Adequacy Study Review</i> – Labrador-Island Link Monthly Update - December 2022," ¹ similar to the December 2, 2022 issue, Hydro has since found two additional broken turnbuckles and unbroken conductors on the ground, one in southern Labrador on Pole 1 and another in the Long Range Mountains on the Island. Repairs have since been completed. ² As mentioned, a root-cause investigation into each of the noted issues is underway. The information from the root-cause investigations will be used to determine appropriate mitigation measures and/or corrective actions to be implemented. Following the completion
14 15 16 17 18 19 20 21 22 23 24 25	b)	Repairs to the damage discovered on December 2, 2022 have been completed; however, the root cause analysis is ongoing, as Hydro has experienced similar issues elsewhere on the line. As reported in the <i>"Reliability and Resource Adequacy Study Review</i> – Labrador-Island Link Monthly Update - December 2022," ¹ similar to the December 2, 2022 issue, Hydro has since found two additional broken turnbuckles and unbroken conductors on the ground, one in southern Labrador on Pole 1 and another in the Long Range Mountains on the Island. Repairs have since been completed. ² As mentioned, a root-cause investigation into each of the noted issues is underway. The information from the root-cause investigations will be used to determine appropriate mitigation measures and/or corrective actions to be implemented. Following the completion of the root-cause investigations for each issue, Hydro will be in a better position to examine

¹ "Reliability and Resource Adequacy Study Review – Labrador-Island Link Monthly Update - December 2022," Newfoundland and Labrador Hydro, January 12, 2023, p. 3.

² "*Reliability and Resource Adequacy Study Review* – Labrador-Island Link Monthly Update - January 2023," Newfoundland and Labrador Hydro, February 2, 2023, p. 3.