

- 1 **Q. Was the runner removed at the time of the March 2016 incident? If so, was the**
2 **keyway deformation noted at that time?**
3
- 4 A. Following the March 2016 incident, the runner was removed to have the seal areas
5 repaired and the new seal ring installed. Removing the runner necessitated removal of
6 the key. Had there been any material deformation of the keyway at that time, it would
7 have been noted, as this would have made it difficult to remove the key. The key was
8 removed without difficulty, and the keyway appeared unaffected by the incident.