

1 Q. Following the March 4, 2015 outage event Hydro implemented practices which
2 impacted the utilization of standby generation. Please provide details of any
3 changes made to operating requirements and/or maintenance strategy for the
4 Holyrood CT following the implementation of these practices.

5

6

7 A. Following the March 4, 2015 outage event, which primarily impacted the Avalon
8 Peninsula, Hydro reviewed its transmission reliability criteria and commenced the
9 practice of operating standby generating units that support the Avalon in advance
10 of Avalon transmission system contingencies, rather than starting its standby
11 generating units after the event has occurred. To provide for this enhanced
12 customer reliability, the starting and operating requirements for the Avalon standby
13 generation, including the Holyrood CT has increased. This change in starting and
14 operating requirements does not change the manufacturer's recommended
15 maintenance strategy for the Holyrood CT. Rather, the timing of the maintenance
16 interventions within this strategy was impacted as a result of increased utilization.