	_	5 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
1	Q.	Re: Holyrood: Upgrade Unit 1 Stack Breech	าเทฐ

What corrective maintenance was needed for the Unit 1 stack breeching for 2007 to

3 present, described by year (see Table 1: Maintenance History).

4 5

6 A. Corrective maintenance was performed for the period 2007 to 2010, and the 2011 7 work is included in this proposal. The work items consisted of internal cleaning,

limited insulation block replacement, patching of steel casing and touch-up painting

on external surfaces of steel casing.

10 11

8

9

The following table indicates the work items for each year:

12

Year	Corrective Maintenance
	- internal ash and deteriorated materials removed
2007	<ul> <li>40 new insulating blocks installed</li> </ul>
	<ul> <li>steel patches installed in exterior of casing to cover holes</li> </ul>
	<ul> <li>touch-up painting of casing patched.</li> </ul>
2008	<ul> <li>internal ash and deteriorated materials removed</li> </ul>
	<ul> <li>285 insulating blocks installed</li> </ul>
2009	- no corrective maintenance performed
2010	<ul> <li>internal ash and deteriorated materials removed</li> </ul>
=326	<ul> <li>holes in steel casing patched with mastic</li> </ul>

13

14

<u>Note:</u> Corrective maintenance was limited in 2009 and 2010 anticipating that the capital project would be approved for completion in 2011.

15