Undertaking 117

To check to see if there was a nitrogen blanket applied in the storage of the appropriate components of this package (If it was requested, and - first, if it was requested, was it actually in place?)

Please refer to Hydro's response to GT-DD-NLH-033.