

1 Q. **Volume II, Exhibit 11: Depreciation Study**

2 What portion of the Original Cost December 31, 2015 shown in Table 1A for
3 accounts T10, T11 and T12, respectively, is associated with the OEM recommended
4 inspections of the Holyrood Combustion Turbine outlined in Table 1 on Page 5 of
5 the report Combustor Inspection Major and Overhaul filed with Hydro's
6 supplemental capital budget application dated August 31, 2016? (Volume II (1st
7 Revision), Exhibit 11: Depreciation Study, Page 47 of 628, Table 1A)

8

9

10 A. The December 31, 2015 Original Cost shown in Table 1A for accounts T10, T11 and
11 T12 do not include any inspections outlined in Table 1 on Page 5 of the Combustor
12 Inspection and Major Overhaul report as the project was done over the period from
13 October 1, 2016 to December 31, 2016 (Page i, line 23) and therefore would not
14 have been included in the 2015 balance.