

1 Q. **Reference: Tab 16; Volume II: Additions for Load – Wabush Substation Upgrades**

2 Please provide a listing (including dates, system conditions at the time, and procedures followed  
3 to resolve the issue) of prior instances when either T3, T4, T5, or T6 within the Wabush  
4 substation were overloaded when the substation was designated as distribution.

5

6

7 A. There are no known prior instances when either of the Wabush Substation transformers were  
8 overloaded according to distribution transformer power ratings. A scenario where the largest  
9 transformer, T6, is out of service while the station is experiencing peak load conditions has not  
10 yet been encountered.