

1 Q. Reference: *Gas Generator Engine Refurbishments Hardwoods and Stephenville*,
2 Page 7, lines 5-6:

3

4 *“Hardwoods End A engine, serial no. 202205, was overhauled in 2010 as a result of*
5 *turbine blade damage.”*

6

7 Is the cost associated with the 2010 engine overhaul included in the Plant Life
8 Extension Program cost identified in Table 1?

9

10

11 A. No, the cost of the 2010 engine overhaul is not included in Table 1. The overhaul of
12 Engine 202205 was a separate supplemental capital project completed at an actual
13 cost of \$1,269,000. Engine 202205 was removed from the Stephenville plant and
14 installed in the Hardwoods plant after the overhaul was completed. For a
15 comprehensive list of capital projects for Stephenville and Hardwoods Gas Turbine
16 Plants from 2007 to 2015 inclusive, please refer to Hydro’s response to NP-NLH-
17 014.