

1 Q. Reference: *Gas Generator Engine Refurbishments Hardwoods and Stephenville*,
2 Page 14, line 11 to Page 15, line 5.

3

4 Are the costs associated with the leased replacement engine included in the
5 \$3,047,100 capital cost estimate for this project?

6

7

8 A. No. The costs associated with the leased replacement engine are not included in
9 the \$3,047,100 capital cost estimate for this project.