

1 Q. Reference: *Gas Generator Engine Refurbishments Hardwoods and Stephenville*,  
2 Page 14, line 11 to Page 15, line 5.

3

4 Further to Request for Information NP-NLH-010, to what extent does Hydro expect  
5 the cost associated with the Stephenville engine to be covered by the warranty?

6

7

8 A. The process to determine root cause is currently in progress. Hydro is unable to  
9 comment on the extent to which the cost associated with the Stephenville engine  
10 (202204) will be covered by the warranty until the root cause is determined.