

1 Q. (Re: *2016 Standby Fuel Deferral Application*, February 5, 2016 Report, Page 8, Lines  
2 1 to 8) Reference is made to boiler tube failures in January, 2016 in Unit 2 and  
3 Hydro's assessment that it does not consider it appropriate to operate Units 1 and 2  
4 at the maximum capacities until full replacement can be made during the annual  
5 maintenance outages of 2016. Please detail Hydro's testing and maintenance  
6 regime as it relates to the testing and maintenance of boiler tubes.

7

8

9 A. Please see Hydro's response to PUB-NLH-001.