

1 Q. **B-5, Upgrade Stack Breeching Unit 1, \$3,553,400**

2 In the report entitled “Upgrade Unit 1 Stack Breeching” located at Tab 2 of Volume
3 1, at page A-7, there is a significant gap in inspection and maintenance records
4 identified for the operating period 1992 –2000. Please provide reasons why this
5 information has not been provided for this period.

6

7

8 A. This proposal has been revised. Please refer to the report attached to Hydro’s
9 letter dated October 26, 2010. Please note that references to information that is
10 responsive to each of the Information Requests can be found in the footnotes of
11 this report.