

1 Q. **B-5, Upgrade Stack Breeching Unit 1, \$3,553,400**

2 In the report entitled "Upgrade Unit 1 Stack Breeching" located at Tab 2 of Volume  
3 1, at page A-7, there is a significant gap in inspection and maintenance records  
4 identified for the operating period 1992 –2000. Please provide reasons why this  
5 information has not been provided for this period.

6

7

8 A. Please see response to IC-NLH-16.