Page 1 of 1

| 1 | Q: | Reference: Review of Newfoundland and Labrador Hydro Power Supply |
|----|----|---|
| 2 | | Adequacy and Reliability Prior to and Post Muskrat Falls Final Report, Page 2-3. |
| 3 | | |
| 4 | | "As directed by the Board for the scope of the phase two investigation, we did not |
| 5 | | address detailed technical information or project engineering and construction |
| 6 | | issues, except as necessary to understand the reliability risks associated with the |
| 7 | | interconnection to the IIS." |
| 8 | | |
| 9 | | Please describe the extent to which Liberty performed any calculations to verify |
| 10 | | the 1:150 and 1:500 return periods depicted in the response to Request for |
| 11 | | Information NP-NLH-004. |
| 12 | | |
| 13 | | |
| 14 | | |
| 15 | A. | Liberty did not perform any calculations, nor seek to verify by other means, the |
| 16 | | 1:150 and 1:500 return periods in the response to NP-NLH-004. |