

1 Q. **Depreciation**

2 Exhibit 11 page 47 of 628. Please explain the difference between T10 (Holyrood Gas
3 Turbine – Combustor Overhaul) and T12 (Holyrood Gas Turbine – Combustor
4 Overhaul)

5

6

7 A. There is an error in the Depreciation Study on the title of T12 – “Holyrood Gas

8 Turbine – Combustor Overhaul” should have read “Holyrood Gas Turbine –

9 Compressor Overhaul.” Please refer to Revision 2 of the 2017 General Rate

10 Application, Volume II, Exhibit 11, page 52 of 633 which was filed on October 16,

11 2017 for the amended naming convention.