

1 Q. **Load Forecast, Generation, and Purchases**

2 Volume I, section 3.21. Hydro states that “The lower volume of power purchases in
3 2016 and 2017 is primarily due to reservoir conditions, inflows, unanticipated plant
4 outages (e.g., the flooding of the Bishop’s Falls powerhouse during Hurricane
5 Matthew in 2016)”. Please provide details if there were any insurance proceeds
6 received for the outages, and if such proceeds address only facility repair versus
7 business interruption and lost generation.

8

9

10 A. There were no insurance proceeds received for this event as the costs were less
11 than the deductibles under the applicable policy.