

1 Q. Please provide copies of all reports, assessments and analyses, whether generated  
2 by Hydro internally or commissioned by Hydro from an external source, which  
3 consider or discuss the options for decommissioning or replacement of the  
4 Hardwoods Gas Turbine plant and Stephenville Gas Turbine plant.

5

6

7 A. In 2007, Hydro engaged Stantec to complete a condition assessment and life cycle  
8 cost analysis of the Hardwoods and Stephenville gas turbine facilities. Please see  
9 the response to NP-NLH-013 for a copy of this report.