

1 Q. Reference: *Gas Generator Engine Refurbishments Hardwoods and Stephenville*,  
2 Page 3, lines 15-20:

3

4 *“The engine was removed from the plant and replaced, on an interim basis, with a*  
5 *leased spare unit provided by Alba Power Ltd. The leased unit is of smaller*  
6 *generation capacity (19MW vs 25MW) than the one being replaced, but fit the*  
7 *installation berth and was readily available for the quickest in-service date during*  
8 *the winter period. The cost of the leased unit is \$4,000 per week plus \$42 for each*  
9 *hour of operation.”*

10

11 On September 3, 2015, Hydro filed an application for the approval of the  
12 Hardwoods Gas Turbine Engine Refurbishment. In its response to Request for  
13 Information NP-NLH-008 of that application, Hydro indicated that a replacement  
14 engine was being leased from Alba Power at a cost of \$16,000 per month. Is the  
15 leased spare unit currently in service at Hardwoods replacing engine serial number  
16 202225 the same unit as referred to in Request for Information NP-NLH-008?

17

18

19 A. Yes, the leased engine currently installed in Hardwoods replacing engine serial  
20 number 202205 is the same leased engine referred to in Request for Information  
21 NP-NLH-008.