Page 1 of 1

| 1 | Q. | Re: IC-NLH-16, B-5, Upgrade Stack Breeching Unit 1, \$3,553,400 |
|---|----|---|
| 2 | | Please provide any details on the revised scope of work that may be available at this |
| 3 | | time. |
| 4 | | |
| 5 | | |
| 6 | A. | Hydro is preparing a scope of work in consultation with a contractor to refurbish |
| 7 | | the breeching and will retain the steel casing but patch it in areas where excessive |
| 8 | | plate thinning has occurred due to corrosion. New thermal insulation system, |
| 9 | | structural supports and expansion joints will be required. |