

1 Q. **Reference: Failure Investigation Report – L3501/2 Tower and Conductor Damage, Icing Event**
2 **January 2021 in Labrador (January 2021 Icing Event Report), page 73.**

3 Has the testing of the suspension clamps been concluded? If so, what were the results? If not,
4 when will the testing be complete?

5

6

7 A. Testing is ongoing on the suspension clamps. The suspension clamps performance will not
8 change the overall result of the failure investigation; however, the testing is being completed to
9 verify that there are no material issues that could have contributed to the failure. The testing is
10 expected to be completed in the fourth quarter of 2021.