

- 1 **Q. (Reference Application, 2.1 2025 Substation Refurbishment and**
2 **Modernization, page 18) It is stated “*To date, 37 substations have been***
3 ***equipped with surveillance and alarm systems to deter theft and vandalism.*”**
4 **Please provide a comparison of theft and vandalism at the substations before**
5 **and after installation of surveillance and alarm systems. Have any arrests**
6 **been made as a result of the surveillance systems?**
7
- 8 A. Six out of 37 substations have experienced a break-in after a surveillance system was
9 installed. Of these six break-ins, four resulted in equipment theft or vandalism. To
10 Newfoundland Power’s knowledge, no arrests have been made as a result of the
11 surveillance system.